

School Environmental Inspection Summary For 2007 - 2008

School Name: Channing Elementary School
Address: 35 Sunnyside Street, Hyde Park, MA 02136
Date of inspection: 11/19/2007
Inspector(s): Jeff Lane
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 8/31/2007
Number of areas: 37
Number of areas inspected: 33
Source of Drinking Water: Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	8	22.9%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	0	0.0%
Dust	1	2.9%
Cleaning needed	0	0.0%
Repairs needed	20	57.1%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	384	688
CO level	0 - 9 ppm	1.6	2.3
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³		
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	36.9	66.4

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	6
Total number of urinals	10
Number of non-functioning urinals	0
Total number of toilets	31
Number of non-functioning toilets	0
Number with bad stall doors	5
Number of toilets without toilet paper	0
Number of bathroom sinks	11
Number of broken sinks	1
Number of soap dispensers	8
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

