

School Environmental Inspection Summary For 2007 - 2008

School Name: Charlestown High School
Address: 240 Medford Street, Charlestown, MA 02129
Date of inspection: 1/18/2008
Inspector(s): Heather Strauss
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged:
Number of areas: 112
Number of areas inspected: 90
Source of Drinking Water: Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	17	18.7%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	9	9.9%
Dust	2	2.2%
Cleaning needed	0	0.0%
Repairs needed	17	18.7%
Improper Chemical Storage	1	1.1%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	410	955
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.017	0.01
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	38.2	73.8

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	12
Total number of urinals	15
Number of non-functioning urinals	1
Total number of toilets	24
Number of non-functioning toilets	1
Number with bad stall doors	1
Number of toilets without toilet paper	2
Number of bathroom sinks	22
Number of broken sinks	3
Number of soap dispensers	21
Number of broken dispensers	0
Percent of bathrooms without adequate soap	25.0%
Percent of bathrooms without paper towels	0.0%

