

School Environmental Inspection Summary For 2007 - 2008

School Name: Eliot K-8 School
Address: 16 Charther Street, Boston MA 02113
Date of inspection: 10/30/2007
Inspector(s): Maria Carvalho
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged:
Number of areas: 28
Number of areas inspected: 28
Source of Drinking Water: Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	0	0.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	1	3.4%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	0	0.0%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm		629
CO level	0 - 9 ppm		0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³		0.02
VOC level	150 – 300 ppb		0
Temperature	68 – 75 degrees		58.8

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	2
Total number of urinals	14
Number of non-functioning urinals	0
Total number of toilets	22
Number of non-functioning toilets	1
Number with bad stall doors	6
Number of toilets without toilet paper	22
Number of bathroom sinks	11
Number of broken sinks	0
Number of soap dispensers	5
Number of broken dispensers	3
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

