

## School Environmental Inspection Summary For 2007 - 2008

**School Name:** English High School  
**Address:** 144 McBride Street, Jamiaca Plain 02130  
**Date of inspection:** 12/28/2007  
**Inspector(s):** Michael DiLorenzo  
**Has Written IPM Program in Office:**  
**Date of Last IPM Activity Logged:**  
**Number of areas:** 97  
**Number of areas inspected:** 75  
**Source of Drinking Water:** Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	3	4.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	4	5.3%
Clutter	0	0.0%
Dust	1	1.3%
Cleaning needed	0	0.0%
Repairs needed	7	9.3%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO <sub>2</sub> level	375 – 1,000 ppm		623
CO level	0 - 9 ppm		0
PM <sub>10</sub> (airborne dust) level	0.00 - .05 mg/m <sup>3</sup>		0.023
VOC level	150 – 300 ppb		23
Temperature	68 – 75 degrees		71.8

<b>Bathrooms: Items/Conditions</b>	
Number of bathrooms inspected:	9
Total number of urinals	5
Number of non-functioning urinals	0
Total number of toilets	22
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	20
Number of bathroom sinks	20
Number of broken sinks	0
Number of soap dispensers	19
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

