

School Environmental Inspection Summary For 2007 - 2008

School Name: Hernandez School (K-8)
Address: 61 School Street, Roxbury MA 02119
Date of inspection: 2/22/2008
Inspector(s): Michael DiLorenzo
Has Written IPM Program in Office:
Date of Last IPM Activity Logged:
Number of areas: 36
Number of areas inspected: 36
Source of Drinking Water: City Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	7	18.9%
Visible Mold Growth	0	0.0%
Overt Pest Sign	4	10.8%
Clutter	4	10.8%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	8	21.6%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	400	521
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.023	0.025
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	31	69.9

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	3
Total number of urinals	16
Number of non-functioning urinals	0
Total number of toilets	27
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	27
Number of bathroom sinks	5
Number of broken sinks	0
Number of soap dispensers	5
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

