

School Environmental Inspection Summary For 2007 - 2008

School Name: Holland Elementary School
Address: 85 Olney Street, Dorchester, MA 02125
Date of inspection: 1/8/2008
Inspector(s): Maria Carvalho
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 12/18/2007
Number of areas: 100
Number of areas inspected: 98
Source of Drinking Water: City Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	0	0.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	0	0.0%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	6	6.1%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	435	640
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.067	0.035
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	49	73.1

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	27
Total number of urinals	20
Number of non-functioning urinals	1
Total number of toilets	39
Number of non-functioning toilets	2
Number with bad stall doors	0
Number of toilets without toilet paper	8
Number of bathroom sinks	47
Number of broken sinks	2
Number of soap dispensers	35
Number of broken dispensers	4
Percent of bathrooms without adequate soap	25.9%
Percent of bathrooms without paper towels	0.0%

