

## School Environmental Inspection Summary For 2007 - 2008

**School Name:** Jackson/Mann School (K-8)  
**Address:** 40 Armington Street, Allston, MA 02134  
**Date of inspection:** 1/16/2008  
**Inspector(s):** Heather Strauss  
**Has Written IPM Program in Office:** Y  
**Date of Last IPM Activity Logged:** 1/14/2008  
**Number of areas:** 99  
**Number of areas inspected:** 87  
**Source of Drinking Water:** Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	14	15.9%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	11	12.5%
Dust	0	0.0%
Cleaning needed	2	2.3%
Repairs needed	40	45.5%
Improper Chemical Storage	1	1.1%

	Normal Indoor Range	Average outside the school	Average inside the school
CO <sub>2</sub> level	375 – 1,000 ppm	467	826
CO level	0 - 9 ppm	0	0
PM <sub>10</sub> (airborne dust) level	0.00 - .05 mg/m <sup>3</sup>		0.02
VOC level	150 – 300 ppb		
Temperature	68 – 75 degrees	27.6	71.9

<b>Bathrooms: Items/Conditions</b>	
Number of bathrooms inspected:	23
Total number of urinals	11
Number of non-functioning urinals	0
Total number of toilets	34
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	1
Number of bathroom sinks	36
Number of broken sinks	5
Number of soap dispensers	24
Number of broken dispensers	0
Percent of bathrooms without adequate soap	8.7%
Percent of bathrooms without paper towels	0.0%

