

School Environmental Inspection Summary For 2007 - 2008

School Name: Lyndon School (K-8) (Pilot School)
Address: 20 Mt. Vernon Street, West Roxbury MA 02132
Date of inspection: 12/14/2007
Inspector(s): Michael DiLorenzo
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 10/19/2007
Number of areas: 54
Number of areas inspected: 50
Source of Drinking Water: City Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	0	0.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	2	3.8%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	11	21.2%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm		565
CO level	0 - 9 ppm		0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³		0.037
VOC level	150 – 300 ppb		25
Temperature	68 – 75 degrees		74.9

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	10
Total number of urinals	12
Number of non-functioning urinals	0
Total number of toilets	26
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	25
Number of bathroom sinks	21
Number of broken sinks	0
Number of soap dispensers	21
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

