

School Environmental Inspection Summary For 2007 - 2008

School Name: Lyon K - 8 School
Address: 50 Beechcroft Street, Brighton, MA 01235
Date of inspection: 11/2/2007
Inspector(s): Heather Strauss
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 10/16/2007
Number of areas: 25
Number of areas inspected: 25
Source of Drinking Water: Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	5	19.2%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	6	23.1%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	1	3.8%
Improper Chemical Storage	1	3.8%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	380	666
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.014	0.021
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	48	71.1

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	4
Total number of urinals	3
Number of non-functioning urinals	0
Total number of toilets	9
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	0
Number of bathroom sinks	6
Number of broken sinks	0
Number of soap dispensers	4
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

