

## School Environmental Inspection Summary For 2007 - 2008

**School Name:** McCormack Middle School  
**Address:** 315 Mt. Vernon Street, Dorchester MA 02125  
**Date of inspection:** 2/8/2008  
**Inspector(s):** Michael DiLorenzo  
**Has Written IPM Program in Office:** Y  
**Date of Last IPM Activity Logged:** 2/1/2008  
**Number of areas:** 65  
**Number of areas inspected:** 46  
**Source of Drinking Water:** Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	4	8.3%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	2	4.2%
Dust	8	16.7%
Cleaning needed	0	0.0%
Repairs needed	5	10.4%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO <sub>2</sub> level	375 – 1,000 ppm	500	924
CO level	0 - 9 ppm	0	0
PM <sub>10</sub> (airborne dust) level	0.00 - .05 mg/m <sup>3</sup>	0.023	0.023
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	35	62.8

<b>Bathrooms: Items/Conditions</b>	
Number of bathrooms inspected:	7
Total number of urinals	22
Number of non-functioning urinals	0
Total number of toilets	28
Number of non-functioning toilets	0
Number with bad stall doors	2
Number of toilets without toilet paper	27
Number of bathroom sinks	29
Number of broken sinks	0
Number of soap dispensers	12
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

