

School Environmental Inspection Summary For 2007 - 2008

School Name: McKinley Technical High School
Address: 97 Peterborough Street, Boston, 02215
Date of inspection: 1/22/2008
Inspector(s): Maria Carvalho
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 8/22/2007
Number of areas: 26
Number of areas inspected: 26
Source of Drinking Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	0	0.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	3	11.1%
Clutter	1	3.7%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	0	0.0%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	395	795
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.018	0.059
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	28	73.1

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	2
Total number of urinals	6
Number of non-functioning urinals	0
Total number of toilets	7
Number of non-functioning toilets	0
Number with bad stall doors	5
Number of toilets without toilet paper	4
Number of bathroom sinks	4
Number of broken sinks	0
Number of soap dispensers	2
Number of broken dispensers	0
Percent of bathrooms without adequate soap	50.0%
Percent of bathrooms without paper towels	0.0%

