

## School Environmental Inspection Summary For 2007 - 2008

**School Name:** Mendell Elementary School  
**Address:** 164 School Street, Roxbury MA 02119  
**Date of inspection:** 1/10/2008  
**Inspector(s):** Michael DiLorenzo  
**Has Written IPM Program in Office:** Y  
**Date of Last IPM Activity Logged:** 9/12/2007  
**Number of areas:** 24  
**Number of areas inspected:** 23  
**Source of Drinking Water:** City Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	5	21.7%
Visible Mold Growth	0	0.0%
Overt Pest Sign	5	21.7%
Clutter	0	0.0%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	4	17.4%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO <sub>2</sub> level	375 – 1,000 ppm		698
CO level	0 - 9 ppm		0
PM <sub>10</sub> (airborne dust) level	0.00 - .05 mg/m <sup>3</sup>		0.026
VOC level	150 – 300 ppb		0
Temperature	68 – 75 degrees		72

<b>Bathrooms: Items/Conditions</b>	
Number of bathrooms inspected:	2
Total number of urinals	8
Number of non-functioning urinals	0
Total number of toilets	13
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	13
Number of bathroom sinks	8
Number of broken sinks	0
Number of soap dispensers	7
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

