

## School Environmental Inspection Summary For 2007 - 2008

**School Name:** Mission Hill School  
**Address:** 67 Alleghany Street, Roxbury, MA 02120  
**Date of inspection:** 1/14/2008  
**Inspector(s):** Heather Strauss  
**Has Written IPM Program in Office:** Y  
**Date of Last IPM Activity Logged:**  
**Number of areas:** 26  
**Number of areas inspected:** 24  
**Source of Drinking Water:** Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	1	4.0%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	3	12.0%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	2	8.0%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO <sub>2</sub> level	375 – 1,000 ppm	400	493
CO level	0 - 9 ppm	0	0
PM <sub>10</sub> (airborne dust) level	0.00 - .05 mg/m <sup>3</sup>	0.023	2.393
VOC level	150 – 300 ppb	0	0
Temperature	68 – 75 degrees	32	70.9

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	2
Total number of urinals	6
Number of non-functioning urinals	0
Total number of toilets	14
Number of non-functioning toilets	1
Number with bad stall doors	1
Number of toilets without toilet paper	0
Number of bathroom sinks	4
Number of broken sinks	0
Number of soap dispensers	2
Number of broken dispensers	0
Percent of bathrooms without adequate soap	0.0%
Percent of bathrooms without paper towels	0.0%

