

School Environmental Inspection Summary For 2007 - 2008

School Name: Murphy School (K-8)
Address: 1 Worrell Street, Dorchester 02122
Date of inspection: 2/13/2008
Inspector(s): Jeff Lane
Has Written IPM Program in Office: N
Date of Last IPM Activity Logged:
Number of areas: 143
Number of areas inspected: 132
Source of Drinking Water: City Water

| Environmental Issue | Number of areas with the Condition | Percentage of areas inspected with the condition |
|---------------------------|------------------------------------|--|
| Leaks/Water Stains | 48 | 35.8% |
| Visible Mold Growth | 1 | 0.7% |
| Overt Pest Sign | 0 | 0.0% |
| Clutter | 3 | 2.2% |
| Dust | 8 | 6.0% |
| Cleaning needed | 4 | 3.0% |
| Repairs needed | 69 | 51.5% |
| Improper Chemical Storage | 0 | 0.0% |

| | Normal Indoor Range | Average outside the school | Average inside the school |
|--|------------------------------|----------------------------|---------------------------|
| CO ₂ level | 375 – 1,000 ppm | 424 | 965 |
| CO level | 0 - 9 ppm | 0.1 | 0.3 |
| PM ₁₀ (airborne dust) level | 0.00 - .05 mg/m ³ | | |
| VOC level | 150 – 300 ppb | | |
| Temperature | 68 – 75 degrees | 38.7 | 71.9 |

| Bathrooms: Items/Conditions | |
|--|------|
| Number of bathrooms inspected: | 34 |
| Total number of urinals | 13 |
| Number of non-functioning urinals | 0 |
| Total number of toilets | 56 |
| Number of non-functioning toilets | 1 |
| Number with bad stall doors | 0 |
| Number of toilets without toilet paper | 0 |
| Number of bathroom sinks | 53 |
| Number of broken sinks | 4 |
| Number of soap dispensers | 51 |
| Number of broken dispensers | 0 |
| Percent of bathrooms without adequate soap | 0.0% |
| Percent of bathrooms without paper towels | 0.0% |

