

School Environmental Inspection Summary For 2007 - 2008

School Name: Sarah Greenwood School (K-8)
Address: 189 Glenway Street, Dorchester, MA 02121
Date of inspection: 1/4/2008
Inspector(s): Jeff Lane
Has Written IPM Program in Office: Y
Date of Last IPM Activity Logged: 9/17/2007
Number of areas: 61
Number of areas inspected: 55
Source of Drinking Water: Bottled Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	6	10.5%
Visible Mold Growth	1	1.8%
Overt Pest Sign	0	0.0%
Clutter	8	14.0%
Dust	0	0.0%
Cleaning needed	3	5.3%
Repairs needed	23	40.4%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	383	1289
CO level	0 - 9 ppm	0	0.1
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³		
VOC level	150 – 300 ppb		
Temperature	68 – 75 degrees	17.3	73.4

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	5
Total number of urinals	22
Number of non-functioning urinals	1
Total number of toilets	41
Number of non-functioning toilets	2
Number with bad stall doors	2
Number of toilets without toilet paper	2
Number of bathroom sinks	14
Number of broken sinks	2
Number of soap dispensers	4
Number of broken dispensers	0
Percent of bathrooms without adequate soap	40.0%
Percent of bathrooms without paper towels	0.0%

