

School Environmental Inspection Summary For 2007 - 2008

School Name: Umana/Barnes Middle School
Address: 312 Border Street, East Boston, MA 02128
Date of inspection: 3/3/2008
Inspector(s): Maria Carvalho
Has Written IPM Program in Office:
Date of Last IPM Activity Logged:
Number of areas: 90
Number of areas inspected: 78
Source of Drinking Water

Environmental Issue	Number of areas with the Condition	Percentage of areas inspected with the condition
Leaks/Water Stains	2	2.5%
Visible Mold Growth	0	0.0%
Overt Pest Sign	0	0.0%
Clutter	0	0.0%
Dust	0	0.0%
Cleaning needed	0	0.0%
Repairs needed	0	0.0%
Improper Chemical Storage	0	0.0%

	Normal Indoor Range	Average outside the school	Average inside the school
CO ₂ level	375 – 1,000 ppm	350	701
CO level	0 - 9 ppm	0	0
PM ₁₀ (airborne dust) level	0.00 - .05 mg/m ³	0.015	0.026
VOC level	150 – 300 ppb		0
Temperature	68 – 75 degrees	37	70.6

Bathrooms: Items/Conditions	
Number of bathrooms inspected:	8
Total number of urinals	9
Number of non-functioning urinals	0
Total number of toilets	15
Number of non-functioning toilets	0
Number with bad stall doors	0
Number of toilets without toilet paper	17
Number of bathroom sinks	21
Number of broken sinks	0
Number of soap dispensers	13
Number of broken dispensers	0
Percent of bathrooms without adequate soap	12.5%
Percent of bathrooms without paper towels	12.5%

